

# DAF XF 106.460 \* EURO6 \* 4X2 \*

## Ogólne cechy

|                           |                   |
|---------------------------|-------------------|
| Marka                     | DAF               |
| model                     | XF 106.460        |
| Podkategoria              | Ciągniki siodłowe |
| Przebieg                  | 749.000km         |
| Rok budowy                | 2016              |
| firstRegistrationDate     | 13-01-2016        |
| Kolor                     | Żółty             |
| Stan                      | Używane           |
| Ogólny stan               | Bardzo dobry      |
| emissionsClass            | Euro 6            |
| advertiserObjectReference | 8./././5,00       |



## Właściwości

|             |                 |
|-------------|-----------------|
| Masa własna | 7.977kg         |
| GVW         | 20.500kg        |
| cabin       | Kabina sypialna |

# DAF XF 106.460 \* EURO6 \* 4X2 \*

## Specyfikacje techniczne

|                        |                            |
|------------------------|----------------------------|
| numberOfAxles          | 2                          |
| shortAxleConfiguration | 4x2                        |
| transmissionType       | transmissionType.automatic |
| power                  | 460hp                      |

## accessories

- Air conditioning
- Aluminium fuel tank
- Leaf spring suspension
- Central locking
- Roof spoiler
- Electrically operated windows
- Refrigerator
- Alloy wheels
- Air horn
- Air suspension
- Fog lights
- Radio/cassette player
- Radio/CD player
- Particulate filter
- Sleeper cab
- Speed limiter
- Stability control
- Vehicle heater
- Heavy duty engine brake
- Visor
- Cabin
- Cruise control
- Catalyst
- Leather interior
- Air suspension system
- Navigation
- Power steering
- Passenger seat
- Metallic paint
- Radio/Cd/Audio system
- Central doorlocking
- Electric windows
- ABS
- EBS
- Climate control
- Heater

- Alarm
- ASR (Anti-Slip Regulation/Traction Control)